

**Product Tested: Safety function "Safe Torque Off"  
(STO) in i950 drive series**

**Safety related modules / components**

| Type Designation                                               | Description                                                    | MP<br>Control board incl. STO | LP<br>Power board                        | Report-No.:        | Certification<br>Status |
|----------------------------------------------------------------|----------------------------------------------------------------|-------------------------------|------------------------------------------|--------------------|-------------------------|
| I95Ax155x1Axxxxxxx<br>I95Ax175x1Axxxxxxx<br>I95Ax222x1Axxxxxxx | i950 BF3 – 0.55 kW<br>i950 BF3 – 0.75 kW<br>i950 BF3 – 2.20 kW | E90ABCMC0000xANP00            | E90ABCLC2224xNFP00                       | 968/FSP 1468.00/17 | <i>Valid</i>            |
| I95Ax240x1Axxxxxxx                                             | i950 BF3 – 4 kW                                                | E90ABCMC0000xANP00            | E90ABCLC4024xNFP00                       | 968/FSP 1468.00/17 | <i>Valid</i>            |
| I95Ax275x1Axxxxxxx<br>I95Ax311x1Axxxxxxx<br>I95Ax315x1Axxxxxxx | i950 BF5 – 7.5 kW<br>i950 BF5 – 11 kW<br>i950 BF5 – 15 kW      | E90ABCMC0000xANP00            | E90ABCLC1134xNFP00<br>E90ABCLC1534xNFP00 | 968/FSP 1468.00/17 | <i>Valid</i>            |
| I95Ax322x1Axxxxxxx                                             | i950 BF6 – 22 kW                                               | E90ABCMC0000xANP00            | E90ABCTC2234xCNP00                       | 968/FSP 1468.01/17 | <i>Valid</i>            |
| I95Ax330x1Axxxxxxx<br>I95Ax345x1Axxxxxxx                       | i950 BF7 – 30 kW<br>i950 BF7 – 45 kW                           | E90ABCMC0000xANP00            | E90ABCTC4534xCNP00<br>E84ACBLN4534x0P000 | 968/FSP 1468.01/17 | <i>Valid</i>            |
| I95Ax355x1Axxxxxxx<br>I95Ax375x1Axxxxxxx                       | i950 BF8 – 55 kW<br>i950 BF8 – 75 kW                           | E90ABCMC0000xANP00            | E90ABCTC7534xCNP00<br>E84ACBLN7534x0P000 | 968/FSP 1468.01/17 | <i>Valid</i>            |
| I95Ax390x1Axxxxxxx<br>I95Ax411x1Axxxxxxx                       | i950 BF9 – 90 kW<br>i950 BF9 – 110 kW                          | E90ABCMC0000xANP00            | E90ABCTC1144xNNP00<br>E50ABCLC1144xNNP00 | 968/FSP 1468.02/18 | <i>Valid</i>            |



## Revision List

referred to on Certificate No.: 01/205/5605.01/22 and  
01/205U/5605.01/22



**Product Tested: Safety function "Safe Torque Off"  
(STO) in i950 drive series**

**Remark: The manufacturer and TÜV Rheinland agree on the revision list as an attachment to the certificate.**

### Revision:

| Date       | Rev. | Description / Changes                                                   | Author  |
|------------|------|-------------------------------------------------------------------------|---------|
| 2017-08-11 | 1.0  | Initial creation (i950 BF 3-5), based on Report-No.: 968/FSP 1468.00/17 | gr/A-FS |
| 2017-11-17 | 1.1  | Update (new i950 BF 6-8), based on Report-No.: 968/FSP 1468.01/17       | gr/A-FS |
| 2018-07-02 | 1.2  | Update (new i950 BF 9), based on Report-No.: 968/FSP 1468.02/18         | gr/A-FS |
| 2022-01-20 | 1.3  | Update (UKCA), based on Report-No.: 968/FSP 1468.03/22                  | jm/A-FS |
| 2022-12-19 | 1.4  | Update for Re-Certification                                             | jm/A-FS |